Return Instructions

Document No. 129-432 October 5, 2009

AQF4150 Replaceable Sensor Tip Calibration Certification

Product Description

The certified sensor tips for the Q-Series Relative Humidity and Relative Humidity & Temperature Sensors are replaceable. Following are the instructions for returning a defective sensor tip if you desire a certificate of calibration for the old tip.

Instructions

- 1. Purchase a new AQF4150 Sensor Tip.
- Complete the following return information, which is on form A465 Ah/Ah (included in the package). A duplicate of this form is on the reverse side of these instructions.


Name: Address: Country: Fax:	Company:
Address:	
Country:	
rdx.	
E maile	

 Enclose the completed form along with the old tip in the shipping carton that the replacement tip was sent in and send to the following address. A return-shipping label is also included in the package. You can use your preferred shipper (post office, DHL, etc.)

SIEMENS Switzerland, Ltd. Building Technologies Group International Headquarters HVAC Products/Sensors Gubelstrasse 22 CH-6301 Zug

Upon receipt of the old tip and the completed form, you will receive a certificate of calibration from SIEMENS Switzerland, Ltd. via e-mail or fax.

Item Number 129-432, Rev. BA



Information in this publication is based on current specifications. The company reserves the right to make changes in specifications and models as design improvements are introduced. Product or company names mentioned herein may be the trademarks of their respective owners. © 2009 Siemens Industry, Inc.